


Conditions :

1. One (1) round hole of 1.5" or less diameter can be made in this zone without any adjustment of the joist capacity.

2. For any other quantity or type of hole, the joist capacity has to be analyzed using TRIFORCE® Analyzer software.



OPENINGS IN THE OSB END PANEL OF A JOIST

DETAIL No.18P